

December 22, 2009

Product withdrawal SAW multimedia filters

In order to streamline the EPCOS product range, the following SAW multimedia filters for TV sets, TV tuners, video and DVD recorders, cable modems, set-top boxes and digital radios are being withdrawn:

| Withdrawn Product | | Substitute Types | |
|-------------------|-----------------|-------------------------------|-------------------------------------|
| Type | Ordering Code | Type | Ordering Code |
| G1865M | B39389G1865M100 | - | - |
| G1875M | B39389G1875M100 | G1975M | B39389G1975M100 |
| G1962M | B39389G1962M100 | G1975M | B39389G1975M100 |
| G1963M | B39389G1963M100 | G1975M | B39389G1975M100 |
| G1984M | B39389G1984M100 | G1975M | B39389G1975M100 |
| G1984N | B39389G1984N201 | - | - |
| G1986M | B39389G1986M100 | G1975M | B39389G1975M100 |
| G1986M | B39389G1986M100 | - | - |
| J1951M | B39395J1951M100 | - | - |
| J1952M | B39389J1952M100 | - | - |
| J1956M | B39389J1956M100 | - | - |
| J1981M | B39389J1981M100 | - | - |
| K2959M | B39380K2959M100 | - | - |
| K2965M | B39380K2965M100 | - | - |
| K2977N | B39389K2977N201 | - | - |
| K2982M | B39389K2982M100 | - | - |
| K2983M | B39380K2983M100 | - | - |
| K3562M | B39380K3562M201 | - | - |
| K3567N | B39380K3567N301 | - | - |
| K3955L | B39380K3955L100 | - | - |
| K3955X | B39380K3955X400 | K3966N | B39380K3966N201 |
| K7265L | B39389K7265L100 | - | - |
| K7267N | B39380K7267N201 | K7267M | B39380K7267M100 |
| K7270N | B39389K7270N201 | K7270M | B39389K7270M100 |
| K7276N | B39380K7276N201 | - | - |
| K7278X | B39380K7278X400 | - | - |
| K7282X | B39380K7282X400 | - | - |
| K7290N | B39380K7290N201 | K7290X | B39380K7290X400 |
| K9350M | B39389K9350M100 | K9358M | B39380K9358M100 |
| K9351N | B39380K9351N201 | ECO type K9358X, K9358M | B39380K9358X400, B39380K9358M100 |
| K9351X | B39380K9351X400 | ECO type K9358X, K9358M | B39380K9358X400, B39380K9358M100 |

EPCOS AG
Corporate Center
St.-Martin-Strasse 53
81669 Munich
P.O.Box 80 17 09
81617 Munich
Germany

Headquarters:
Munich

Commercial register
of the local court
(Amtsgericht): Munich
HRB 127250

Chairman of the Supervisory
Board: Klaus Ziegler

Management Board:
Gerhard Pegam, President & CEO
Joachim Zichlarz
Dr. Werner Faber

**SAW Components,
Modules**

Distribution:
internal / external

091222SAW1e

1/4

| Withdrawn Product | | Substitute Types | |
|-------------------|-----------------|-------------------|-------------------------------------|
| Type | Ordering Code | Type | Ordering Code |
| K9352L | B39380K9352L100 | - | - |
| K9353M | B39389K9353M100 | K9358M | B39380K9358M100 |
| K9358N | B39380K9358N201 | K9358X | B39380K9358X400 |
| K9361L | B39389K9361L100 | - | - |
| K9363N | B39389K9363N201 | K9354N | B39389K9354N201 |
| K9453X | B39389K9453X400 | K9662A | B39389K9662A101 |
| K9461M | B39389K9461M100 | - | - |
| K9661N | B39389K9661N201 | - | - |
| K9663N | B39389K9663N201 | - | - |
| K9664N | B39389K9664N201 | - | - |
| K9664X | B39389K9664X400 | - | - |
| K9750M | B39389K9750M100 | - | - |
| L9353M | B39339L9353M100 | - | - |
| L9353M | B39339L9353M100 | - | - |
| L9453M | B39389L9453M100 | - | - |
| L9653M | B39389L9653M100 | - | - |
| M1865M | B39458M1865M100 | M1971M | B39458M1971M100 |
| M1866M | B39458M1866M100 | M1971M | B39458M1971M100 |
| M1958M | B39458M1958M100 | M1971M | B39458M1971M100 |
| M1962M | B39458M1962M100 | M1971M | B39458M1971M100 |
| M1967L | B39458M1967L100 | - | - |
| M1967M | B39458M1967M100 | M1971M | B39458M1971M100 |
| M1967N | B39458M1967N201 | M1867N | B39458M1867N201 |
| M1973N | B39380M1973N201 | - | - |
| M1980N | B39458M1980N201 | - | - |
| M3561M | B39458M3561M201 | M1971M | B39458M1971M100 |
| M3573N | B39458M3573N301 | M3575N | B39458M3575N301 |
| M3953N | B39458M3953N201 | M3954X, M3953M | B39458M3954X400, B39458M3953M100 |
| M3954M | B39458M3954M100 | M3954X, M3953M | B39458M3954X400, B39458M3953M100 |
| M3954N | B39458M3954N201 | M3954X | B39458M3954X400 |
| M3956L | B39380M3956L100 | - | - |
| M9352M | B39458M9352M100 | M9370M | B39458M9370M100 |
| M9370N | B39458M9370N201 | M9370X | B39458M9370X400 |
| N1951M | B39588N1951M100 | - | - |
| N1952N | B39588N1952N201 | - | - |
| N1955M | B39588N1955M100 | - | - |
| N3511N | B39588N3511N301 | - | - |
| N3512N | B39588N3512N301 | N3512X | B39588N3512X500 |
| N3562N | B39588N3562N301 | N3564X | B39588N3564X500 |

| Withdrawn Product | | Substitute Types | |
|-------------------|-----------------|---------------------------|-------------------------------------|
| Type | Ordering Code | Type | Ordering Code |
| N3564N | B39588N3564N301 | N3564X | B39588N3564X500 |
| N3566N | B39588N3566N301 | N3564X | B39588N3564X500 |
| N9260M | B39588N9260M100 | - | - |
| X6755M | B39327X6755M100 | - | - |
| X6756M | B39234X6756M100 | - | - |
| X6757M | B39399X6757M100 | - | - |
| X6758M | B39470X6758M100 | - | - |
| X6759M | B39253X6759M100 | - | - |
| X6760M | B39272X6760M100 | - | - |
| X6763M | B39352X6763M100 | X6773M | B39352X6773M100 |
| X6766N | B39361X6766N201 | - | - |
| X6766X | B39361X6766X400 | - | - |
| X6767N | B39446X6767N201 | X6767M | B39446X6767M100 |
| X6767X | B39446X6767X400 | X6767M | B39446X6767M100 |
| X6771N | B39570X6771N201 | X6771X | B39570X6771X400 |
| X6776N | B39361X6776N201 | X6776X | B39361X6776X400 |
| X6790N | B39380X6790N201 | X6790X | B39380X6790X400 |
| X6870N | B39440X6870N201 | Eco type for X6866N | B39440X6866N201 |
| X6883M | B39500X6883M100 | - | - |
| X6891N | B39435X6891N201 | - | - |
| X6894N | B39352X6894N201 | X6773M | B39352X6773M100 |
| X6895M | B39360X6895M100 | X6895X | B39360X6895X400 |
| X6931X | B39440X6931X400 | X6941X | B39440X6941X400 |
| X6935N | B39440X6935N201 | - | - |
| X6940N | B39570X6940N201 | X6948X | B39570X6948X400 |
| X6947N | B39440X6947N201 | X6947X | B39440X6947X400 |
| X6948N | B39570X6948N201 | X6948X | B39570X6948X400 |
| X6989N | B39570X6989N201 | X6989X, X6771X | B39570X6989X400, B39570X6771X400 |
| X7001L | B39307X7001L100 | - | |
| X7002L | B39389X7002L100 | - | |
| X7004L | B39440X7004L100 | - | |
| X7054L | B39700X7054L100 | - | |
| X7056L | B39440X7056L100 | - | |
| X7060L | B39361X7060L100 | - | |
| X7256N | B39570X7256N201 | - | |
| Y7102L | B39115Y7102L100 | - | |



UPtoDATE

Deadline for last orders **June 30, 2010**
Last shipments by **September 30, 2010**

Contact Shirlin Tan, SAW MM PM, Singapore

Customers should address inquiries directly to their EPCOS sales contacts.

EPCOS AG
Corporate Center
St.-Martin-Strasse 53
81669 Munich
P.O.Box 80 17 09
81617 Munich
Germany

Headquarters:
Munich

Commercial register
of the local court
(Amtsgericht): Munich
HRB 127250

Chairman of the Supervisory
Board: Klaus Ziegler

Management Board:
Gerhard Pegam, President & CEO
Joachim Zichlarz
Dr. Werner Faber

**SAW Components,
Modules**

Distribution:
internal / external

091222SAW1e